

Why you must Flush your Power Steering System Prior to Installing New Components.



Pump Housing before reservoir installed. Note Magnet on housing to catch metal particles.

Below is the same pump with Metal Particles left in the system which now covered the magnet and then the excess metal gets into the valve and causes the unit to fail. This failure occurred within a day of the installation of our Pump because the customer did not flush the system.



Metal from old System on Magnet